


Mounting Instruction

SHV Cable Jack + Cable RG 58

1 Remove the cable sheath




2 Push back the braided shield and strip the isolation from the center conductor




3 Push back the screen to the front end and twist it together




4 Put on the cable the screws, metal washer, clamping rubber and taper washer



5 Push back the braided shield and cut it along the outside of the taper washer



6 Solder the center contact



7 Push the parts together and screw them together

